


**MERCEDES A: 1GSZ557**

|                                   |                          |              |                                  |
|-----------------------------------|--------------------------|--------------|----------------------------------|
| Vinnnumber:                       | <b>WDD1760121V014799</b> | Versionname: | <b>A 180CDI BE Edition 109PK</b> |
| First Registrationdate:           | <b>22/04/2014</b>        | Fiscalpower: |                                  |
| Expertise Mileage:                | <b>176830</b>            | Power Kw:    | <b>80</b>                        |
| Bodytype:                         |                          | Body color   | <b>Grey</b>                      |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                   |
| Transmission:                     |                          | Rims summer  | <b>Aluminium</b>                 |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                        |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>3612</b>                      |
| Number of doors                   | <b>5</b>                 |              |                                  |
| Number of seats                   | <b>5</b>                 |              |                                  |
| Number head rests                 | <b>5</b>                 |              |                                  |
| Rims summer                       | <b>Aluminium</b>         |              |                                  |
| Category                          | <b>Passenger Car</b>     |              |                                  |
| Oil level                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                  |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             |                              |
| Steering wheel multifunctional |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Dunlop: 8 mm</b>      | Fr.R. | <b>Dunlop: 8 mm</b>      |
|               | Re.L.                            | <b>Continental: 7 mm</b> | Re.R. | <b>Continental: 7 mm</b> |

**Assistance equipment**


|            |           |            |           |
|------------|-----------|------------|-----------|
| Repair kit | <b>No</b> | Compressor | <b>No</b> |
|------------|-----------|------------|-----------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>490,08</b> |
|-------------------|---------------|

|                           |              |
|---------------------------|--------------|
| Interior, Dirty, Cleaning | <b>50,00</b> |
|---------------------------|--------------|



|                                                             |               |
|-------------------------------------------------------------|---------------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | <b>290,08</b> |
|-------------------------------------------------------------|---------------|



|                                        |      |
|----------------------------------------|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

|                                       |        |
|---------------------------------------|--------|
| Tyre repair kit, Missing, E - Replace | 150,00 |
|---------------------------------------|--------|

No pictures to display


|                               |      |
|-------------------------------|------|
| Door F R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                         |      |
|-----------------------------------------|------|
| Front bumper, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------------|------|

No pictures to display

|                                  |      |
|----------------------------------|------|
| Door R R, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|



|                                 |      |
|---------------------------------|------|
| Alloy rim F R, Rust, Acceptable | 0,00 |
|---------------------------------|------|

No pictures to display