



BMW X1: 1ESM069			
Vinnnumber:	WBAVP91070VV59517	Versionname:	X1 xDrive20 163PK
First Registrationdate:	8/03/2013	Fiscalpower:	
Expertise Mileage:	70570	Power Kw:	120
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3426
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	225/45/18/95 V LightMetal			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment	
Total cost ex VAT	2039,71
Rearview mirror housing L, Chemical polution, LI - Repair and paint (complete)	115,56



Door R R, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Centre console, Stain, Cleaning	25,00



Alloy rim F R, Scratch(es), E - Replace

235,20



Door F L, Bump(s), LI - Repair and paint (complete)

438,35



Alloy rim F L, Scratch(es), E - Replace

235,20



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), E - Replace

235,20





Alloy rim R R, Scratch(es), E - Replace	235,20
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------

