



SKODA OCTAVIA COMBI: 1LAV947


Vinnnumber:	TMBJF7NEXG0040922	Versionname:	1.6 CRTDI 66KW GREENTEC AMBITION
First Registrationdate:	5/08/2015	Fiscalpower:	
Expertise Mileage:	188668	Power Kw:	66
Bodytype:	Break	Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3233
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	205/55/16/91 H Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1555,23
Bonnet, Bump(s), LI - Repair and paint (complete)			290,08



Bodywork, Not original part, Acceptable	0,00
--	-------------

Trunk lid covering R, Damaged, Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Damaged, Le - Replace and paint	735,00
	
Door F R, Rust, LI - Repair and paint (complete)	318,35
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	