



VOLKSWAGEN Caddy: 1EQD369			
Vinnumber:	WV1ZZZ2KZDX091269	Versionname:	CADDY VAN B/F 102PK
First Registrationdate:	20/02/2013	Fiscalpower:	
Expertise Mileage:	32641	Power Kw:	75
Bodytype:	Transporter	Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3515
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	
GPS storage	HD
GPS storage	
Windows electric F	
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/91 H Steel			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
Spare wheel	Yes
Jack	Yes
Total cost ex VAT	750,60
Trunk door panel R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Smart repair	110,64



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display


Front bumper, Damaged, E - Replace

398,40




Wing R R, Bump(s), PDR - Knock out without painting

63,00



Wing R L, Bump(s), PDR - Knock out without painting

63,00



Trunk door R L, Bump(s), It - Spot repair

115,56



Trunk door R R, Bad repair, Acceptable

0,00

