



VOLVO V70: 1EOX166

Vinnnumber:	YV18W84A1D1270179	Versionname:	V70 D2 Kinetic St/St 115PK
First Registrationdate:	11/02/2013	Fiscalpower:	
Expertise Mileage:	98637	Power Kw:	85
Bodytype:	Break	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3502
Maintenance	GEDAAN OP 93685 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD	Central consol F
TV/DVD screen F	Luggage cover
GPS storage	HD Rear parking sensors
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/96 V LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	305,56
-------------------	---------------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Front bumper, Scratch(es), It - Spot repair

115,56

