


RENAULT Trafic: 1GDV389

Vinnnumber:	VF1JLR1B3EY538186	Versionname:	TRAFIC PAS.Phys.III L2H1
First Registrationdate:	10/01/2014	Fiscalpower:	Bl.Ed.FAP 115PK
Expertise Mileage:	116531	Power Kw:	84
Bodytype:	Bus	Body color	Light Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV19
Number of doors	4		
Number of seats	9		
Number head rests	9		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS portable
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/16/109 R LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Total cost ex VAT	617,97
Door F R, Bump(s), PDR - Knock out without painting	63,00



Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	217,56
---	---------------



Side window R L, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

158,85



Rear window, Scratch(es), E - Replace

0,00



Rocker panel inner F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

115,56



Side window R R, Scratch(es), E - Replace

0,00



Windscreen, Scratch(es), E - Replace

0,00

