



VOLVO V40: 1HPF185			
Vinnnumber:	YV1MZ8451F2061963	Versionname:	V40 Cr.Country D2 Base
First Registrationdate:	4/09/2014	Fiscalpower:	115PK
Expertise Mileage:	111945	Power Kw:	84
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2302
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	205/60/16/92 H Steel			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			658,20
Wheel cover F L, Scratch(es), E - Replace			30,00



Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display	

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		308,20
		
Wheel cover F R, Scratch(es), E - Replace		30,00
		
		
Luggage space cover, Missing, E - Replace		240,00
		
Interior, Dirty, Cleaning		50,00
		
Wing R L, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		