



CITROEN C4 Picasso: 1BKH986			
Vinnnumber:	VF7UD9HR8BJ643325	Versionname:	C4 PICASSO Exclusive FAP BMP 112PK Aut.
First Registrationdate:	21/06/2011	Fiscalpower:	
Expertise Mileage:	189559	Power Kw:	82
Bodytype:	Hatchback	Body color	Red
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1528
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Panoramic roof
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	215/55/16/93 H LightMetal			
	Fr.L.	Fulda: 6 mm	Fr.R.	Fulda: 6 mm
	Re.L.	Fulda: 7 mm	Re.R.	Fulda: 7 mm

Assistance equipment	
Total cost ex VAT	1658,58
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08



Moulding windscreen R, Deformed, Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Bad repair, Paint	0,00
-----------------------------	------




Moulding windscreen L, Deformed, Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------

