



MAZDA 3 SEDAN: 1JUS336			
Vinnnumber:	3MZBM52561M104576	Versionname:	1.5 SKYACTIV-G 100HP ACTIVE
First Registrationdate:	2/03/2015	Fiscalpower:	
Expertise Mileage:	46041	Power Kw:	74
Bodytype:	Berline	Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2614
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		644,57	
Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35	



Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Windscreen, Scratch(es), E - Replace	0,00
--------------------------------------	------



Interior, Smell, Ozone treatment	152,58
----------------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Centre console, Scratch(es), Smart repair	110,64
---	--------



Wing R R, Bad repair, Paint	0,00
-----------------------------	------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display