



FORD TRANSIT CUSTOM: 1BYN279

Vinnumber:WF0ZXXTTGZDRT8512

First Registrationdate:

Expertise Mileage:103635

Bodytype:Transporter

Gearbox:MAN 6 VIT

Transmission:

Fueltype:Diesel

Battery functioning:Yes

Number of doors:5

Number of seats:5

Number head rests:5

Rims summer:Aluminium

Category:Light Commercial Vehicle

Oil level:OK

Registration Certificate Car (BE):Yes

Versionname:

Fiscalpower:

Power Kw:92

Body color:Black

Paint type:Metalic

Rims summer:Aluminium

Oil level:OK

Parking lot:1715

Options

Radio CD

Windows electric F

Cruise Control

Steering wheel multifunctional

Radio multimedia

Type of headlighting:Headlighting Halogen

Type of GPS:GPS big screen color

Type of Lining:Lining fabrics

Type of climate control:Manual climate control

Central consol F

Front parking sensors

Rear parking sensors

Type of Tow bar:Tow bar fixed

Limited Technical Inspection

Airco functioning:OK

Tires wear profile:OK

Idle position:OK

Engine startingtime:OK

Exhaust gass:OK

Handbrake:OK

Battery functioning:Yes

Power steering:Yes

Sound engine:OK

Clutch test:OK

Wiper fluid level:NOT OK

Transmission:OK

Lighting:OK

Wiperblades:OK

Degree of wear

Summer tyres:

215/65/16/109 T LightMetal

Fr.L.Michelin: 5 mm

Fr.R.Michelin: 5 mm

Re.L.Bridgestone: 4 mm

Re.R.Bridgestone: 4 mm

Assistance equipment

Total cost ex VAT

863,59

Trunk lid covering R, Scratch(es), Smart repair

110,64







Door F R, Scratch(es), Acceptable

0,00

No pictures to display


Maintenance book, Missing, E - Replace

0,00


No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting


122,40




Rearview mirror housing L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------



Door F R, Bump(s), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Interior, Dirty, Cleaning	50,00





Bumper F R, Strained , Smart repair

110,64

