



VOLKSWAGEN Touran: 1GKF507

Vinnnumber:	WVGZZZ1TZEW060625	Versionname:	TOURAN Trendline BMT
First Registrationdate:	3/03/2014	Fiscalpower:	St/St DSG 105PK Aut
Expertise Mileage:	110477	Power Kw:	77
Bodytype:		Body color	Beige
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	BINNEN 26300KM	Parking lot	4611
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/94 V LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			877,74
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Bumper corner R R, Scratch(es), It - Spot repair	115,56
---	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Alloy rim R L polished, Scratch(es), E - Replace	235,20
--	--------



Boot cover, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display