



OPEL Astra: 1EWW663			
Vinnnumber:	W0LPE8EW5D8047610	Versionname:	ASTRA BRE ecoFLEX Cosmo St/St 110PK
First Registrationdate:	10/04/2013	Fiscalpower:	
Expertise Mileage:	182107	Power Kw:	81
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3711
Maintenance	DRINGEND		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	225/50/17/98 H LightMetal		
	Fr.L.	Continental: 3 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
		Continental: 3 mm	Continental: 6 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			742,52
Maintenance, Maintenance, Execute			0,00



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Floor covering F L, Hole, Smart repair	64,32
--	-------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display