


VOLVO V40: 1GNE641

Vinnnumber:	YV1MV2051E2146883	Versionname:	V40 T2 Base 120PK
First Registrationdate:	17/03/2014	Fiscalpower:	
Expertise Mileage:	106312	Power Kw:	88
Bodytype:	Hatchback	Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2423
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	549,76
-------------------	---------------

Wing F L, Bad repair, Acceptable	0,00
----------------------------------	-------------

No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair	115,56
--	---------------





Bumper grille F R, Missing, E - Replace

32,40



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Repaired, E - Replace

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Bad repair, Acceptable

0,00

No pictures to display