



VOLKSWAGEN Polo: 1HEY099				
Vinnnumber:	WVWZZZ6RZFY080935	Versionname:	POLO Comfortline BMT 90PK	
First Registrationdate:	3/07/2014	Fiscalpower:		
Expertise Mileage:	121486	Power Kw:	66	
Bodytype:	Hatchback	Body color	Blue	
Gearbox:	MAN 5 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	No			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Type of headlighting	Headlighting Halogen			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tires wear profile	OK	Battery functioning	No	
Engine startingtime	NOT OK	Wiperblades	NOT OK	
Handbrake	OK			
Degree of wear				
Summer tyres:	185/60/15/84 H LightMetal			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT		246,56		
Front bumper, Scratch(es), Acceptable		0,00		
No pictures to display				
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		246,56		
Rearview mirror housing R, Chemical pollution, P - Check		0,00		
Door R R, Chemical pollution, P - Check		0,00		



Roof, Chemical polution, P - Check

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Bump(s), Acceptable

0,00

No pictures to display