


MERCEDES B: 1JHL948

Vinnnumber:	WDD2462121J291882	Versionname:	1.5 B 180 CDI
First Registrationdate:	22/12/2014	Fiscalpower:	
Expertise Mileage:	92950	Power Kw:	80
Bodytype:	Break	Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2824
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1101,70
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door panel R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	---------------



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Roof, Bump(s), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35

