



MERCEDES B: 1EPO877

Vinnumber:	WDD2462001J145199	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	15/02/2013	Fiscalpower:	
Expertise Mileage:	168485	Power Kw:	80
Bodytype:		Body color	Gold
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1232
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	195/65/15/91 H Steel			
	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Semperit: 8 mm	Re.R.	Semperit: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1039,32
Wheel cover F R, Scratch(es), Acceptable			0,00
No pictures to display			
Engine protective plate, Deformed, Acceptable			0,00



Rocker panel inner R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Door R R, Bump(s) and scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Damaged, E - Replace

30,00



Engine, Not original part, Acceptable

0,00



Interior, Stain, Cleaning

100,00



Rear window, Scratch(es), E - Replace

370,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display