



VOLVO V60: 1ESH237

Vinnnumber:	YV1FW84A1D1131743	Versionname:	V60 D2 Kinetic St/St 115PK
First Registrationdate:	7/03/2013	Fiscalpower:	
Expertise Mileage:	103413	Power Kw:	84
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1314
Maintenance	21-9-2017		
Maintenance	92028 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	259,80
-------------------	---------------

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	---------------



Mirror side blinker L, Scratch(es), Acceptable	0,00
--	-------------



Wing F L, Bump(s), Acceptable

0,00



Door panel F L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Tires, Out of tolerance, E - Replace

0,00

No pictures to display