



VOLKSWAGEN Golf: 1EXM151

Vinnnumber:	WVWZZZ1KZDM669811	Versionname:	GOLF BRE Highline
First Registrationdate:	15/04/2013	Fiscalpower:	BlueMot.DPF 105PK
Expertise Mileage:	123236	Power Kw:	77
Bodytype:		Body color	SILVER
Gearbox:	MAN 5 VIT	Body color	Silver
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	3328
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD		Luggage cover
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	0,00
-------------------	------

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rocker panel inner R L, Damaged, Acceptable	0,00
---	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Boot cover, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Not original part, Acceptable	0,00



Maintenance, Maintenance, Acceptable	0,00
--------------------------------------	------



Boot carpet, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Not original part, Acceptable	0,00



Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	