


**VOLKSWAGEN Passat: 1HAZ702**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:                        | <b>WVWZZZ3CZEE170551</b> | Versionname: | <b>PASSAT VAR Comfortline</b> |
| First Registrationdate:            | <b>6/06/2014</b>         | Fiscalpower: | <b>136PK</b>                  |
| Expertise Mileage:                 | <b>137228</b>            | Power Kw:    | <b>100</b>                    |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Grey</b>              |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2813</b>                   |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Sun Roof electric            |
| Windows electric F             | Panoramic roof               |
| Windows electric R             | Central consol F             |
| Cruise Control                 | Luggage cover                |
| Steering wheel multifunctional | Front parking sensors        |
| Seats F heated                 | Rear parking sensors         |
| Radio multimedia               |                              |
| Type of headlighting:          | <b>Headlighting Halogen</b>  |
| Type of GPS:                   | <b>GPS big screen color</b>  |
| Type of Lining:                | <b>Lining leather</b>        |
| Type of climate control:       | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                      |           |                      |            |
|----------------------|-----------|----------------------|------------|
| Airco functioning:   | <b>OK</b> | Battery functioning: | <b>Yes</b> |
| Tires wear profile:  | <b>OK</b> | Power steering:      | <b>Yes</b> |
| Idle position:       | <b>OK</b> | Sound engine:        | <b>OK</b>  |
| Engine startingtime: | <b>OK</b> | Clutch test:         | <b>OK</b>  |
| Exhaust gass:        | <b>OK</b> | Wiper fluid level:   | <b>OK</b>  |
| Handbrake:           | <b>OK</b> | Transmission:        | <b>OK</b>  |
|                      |           | Lighting:            | <b>OK</b>  |
|                      |           | Wiperblades:         | <b>OK</b>  |

**Degree of wear**

|               |                           |             |       |             |
|---------------|---------------------------|-------------|-------|-------------|
|               | 215/55/16/93 H LightMetal |             |       |             |
| Summer tyres: | Fr.L.                     | Fulda: 3 mm | Fr.R. | Fulda: 3 mm |
|               | Re.L.                     | Fulda: 4 mm | Re.R. | Fulda: 4 mm |

**Assistance equipment**

|              |            |       |            |
|--------------|------------|-------|------------|
| Spare wheel: | <b>Yes</b> | Jack: | <b>Yes</b> |
|--------------|------------|-------|------------|

Total cost ex VAT: 1040,41


Door R R, Bump(s), Acceptable: 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete): 220,18



Bumper R, Scratch(es), LI - Repair and paint (complete): 211,80



|                                                         |        |
|---------------------------------------------------------|--------|
| Door F R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---------------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                             |        |
|-------------------------------------------------------------|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|-------------------------------------------------------------|--------|

