



FORD C-MAX: 1FCO200			
Vinnnumber:	WF0JXXWPBJDM16853	Versionname:	C-MAX Trend St/St 95PK
First Registrationdate:	24/05/2013	Fiscalpower:	
Expertise Mileage:	140947	Power Kw:	70
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1124
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	215/55/16/93 V LightMetal		
	Fr.L.	Firestone: 7 mm	Fr.R.
		Firestone: 7 mm	
	Re.L.	Goodyear: 5 mm	Re.R.
		Goodyear: 5 mm	

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			485,54
Bonnet, Bump(s), Acceptable			0,00
No pictures to display			
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R L, Bump(s) and scratch(es), Acceptable			0,00
No pictures to display			
Door F L, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Door moulding Lower F L, Scratch(es), E - Replace	114,00
---	--------



Bonnet, Damaged, I - Repair	67,54
-----------------------------	-------



Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door moulding Lower R L, Scratch(es), E - Replace	114,00
---	--------



Front bumper, Stone chip(s), Acceptable	0,00
---	------

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display