



| RENAULT Clio: 1GVV877             |                   |              |                                     |
|-----------------------------------|-------------------|--------------|-------------------------------------|
| Vinnnumber:                       | VF15RJL0H50895015 | Versionname: | CLIO IV BER e-Expression St&St 90PK |
| First Registrationdate:           | 14/05/2014        | Fiscalpower: |                                     |
| Expertise Mileage:                | 71119             | Power Kw:    | 66                                  |
| Bodytype:                         |                   | Body color   | Light Grey                          |
| Gearbox:                          | MAN 5 VIT         | Paint type   | Metalic                             |
| Transmission:                     |                   | Rims summer  | Steel                               |
| Fueltype:                         | Diesel            | Oil level    | OK                                  |
| Battery functioning               | Yes               | Parking lot  | 2721                                |
| Number of doors                   | 5                 |              |                                     |
| Number of seats                   | 5                 |              |                                     |
| Number head rests                 | 4                 |              |                                     |
| Rims summer                       | Steel             |              |                                     |
| Category                          | Passenger Car     |              |                                     |
| Oil level                         | OK                |              |                                     |
| Registration Certificate Car (BE) | Yes               |              |                                     |

| Options                        |                        |
|--------------------------------|------------------------|
| Windows electric F             | Luggage cover          |
| Cruise Control                 |                        |
| Steering wheel multifunctional |                        |
| Radio multimedia               |                        |
| Type of headlighting           | Headlighting Halogen   |
| Type of GPS                    | GPS big screen color   |
| Type of Lining                 | Lining fabrics         |
| Type of climate control        | Manual climate control |

| Limited Technical Inspection |    |                     |     |
|------------------------------|----|---------------------|-----|
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

| Degree of wear |                      |                   |       |                   |
|----------------|----------------------|-------------------|-------|-------------------|
| Summer tyres:  | 185/65/15/88 T Steel |                   |       |                   |
|                | Fr.L.                | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
|                | Re.L.                | Bridgestone: 6 mm | Re.R. | Bridgestone: 6 mm |

| Assistance equipment                                    |         |
|---------------------------------------------------------|---------|
| Repair kit                                              | Yes     |
| Compressor                                              | Yes     |
| Total cost ex VAT                                       | 1134,68 |
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 246,56  |



|                                                             |        |
|-------------------------------------------------------------|--------|
| Seat cover F L, Dirty, Cleaning                             | 0,00   |
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 169,44 |



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F R, Damaged, E - Replace 24,00

