



BMW X3: 1FFW115			
Vinnnumber:	WBAWY110600C56778	Versionname:	X3 sDrive18 136PK
First Registrationdate:	18/06/2013	Fiscalpower:	
Expertise Mileage:	139248	Power Kw:	100
Bodytype:	SUV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3812
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunction	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/60/17/99 V LightMetal			
	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			984,27
Bonnet, Chemical polution, LI - Repair and paint (complete)			348,09



Moulding windscreen R, Deformed, Acceptable	0,00
---	------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display