



FIAT Fiorino: JG8323			
Vinnnumber:	ZFA22500006855339	Versionname:	FIORINO B/F CARGO Base DPF(EU5) 75PK
First Registrationdate:	13/06/2014	Fiscalpower:	
Expertise Mileage:	137479	Power Kw:	55
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4705
Battery functioning	Yes		
Number of doors	4		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options	
Radio CD	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	175/70/14/84 T Steel			
	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment			
Spare wheel	No	Jack	No
Total cost ex VAT			1230,15
Steel rim R R, Deformed, E - Replace			72,60



Wing R R, Accident, LI - Repair and paint (complete)		375,15
--	--	--------





Jack, Missing, E - Replace 42,00

No pictures to display

Seat cover F L, Deformed, E - Replace 300,00



Door F L, Bump(s), PDR - Knock out without painting 82,80



Windscreen, Stone chip(s), Windscreen repair 58,80



Steel rim F R, Deformed, E - Replace 72,60



Trunk door R L, Bump(s) and scratch(es), It - Spot repair 115,56



Bumper corner R R, Scratch(es), Smart repair 110,64



Dashboard, Worn, Acceptable 0,00

No pictures to display