



PEUGEOT 508: 1FH0771			
Vinnnumber:	VF38URHC8DL027920	Versionname:	508 SW RXH BMP STT 163PK Aut.
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	80686	Power Kw:	120
Bodytype:	Break	Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Hybrid Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4522
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Type of headlighting	Headlighting Xenon	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining leather	Type of Tow bar	Tow bar removable
Type of climate control	Autom climate control		
Head-up Display			
Sport seats			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	245/45/18/100 Y LightMetal			
	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment	
Total cost ex VAT	1326,51
Windscreen trim, Scratch(es), Acceptable	0,00




Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------




Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), Smart repair 110,64



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



