




RENAULT Espace: 1GDH566			
Vinnnumber:	VF1JKFJA650253487	Versionname:	ESPACE Initiale 149PK
First Registrationdate:	7/01/2014	Fiscalpower:	
Expertise Mileage:	82211	Power Kw:	110
Bodytype:	MPV	Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2106
Number of doors	5		
Number of seats	6		
Number head rests	6		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Seats electric F R
Windows electric F	Panoramic roof
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/55/17/101 W LightMetal		
	Fr.L.	Continental: 6 mm	Fr.R.
	Re.L.	Continental: 7 mm	Re.R.
		Continental: 6 mm	Continental: 7 mm

Assistance equipment	
Total cost ex VAT	846,86
Backrest cover R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Internal Boot Lining L, Damaged, Acceptable	0,00
---	------

No pictures to display

Internal Boot Lining R, Damaged, Acceptable	0,00
---	------

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Backrest cover R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Door panel R R, Damaged, Acceptable	0,00
-------------------------------------	------

No pictures to display