



VOLVO V40: 1GKF700

Vinnnumber:	YV1MV846BE2140849	Versionname:	V40 D2 Base Powershift 115PK Aut.
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	170348	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4424
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 6,5 mm	Fr.R.	Michelin: 6,5 mm
	Re.L.	Pirelli: 3,5 mm	Re.R.	Pirelli: 3,5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	698,35
-------------------	--------

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------






Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display