


**VOLKSWAGEN PASSAT VARIANT: 1JFY651**

|                                   |                          |              |                                        |
|-----------------------------------|--------------------------|--------------|----------------------------------------|
| Vinnnumber:                       | <b>WVWZZZ3CZEE176925</b> | Versionname: | <b>1.6 CR TDI 77KW BMT COMFORTLINE</b> |
| First Registrationdate:           | <b>8/12/2014</b>         | Fiscalpower: |                                        |
| Expertise Mileage:                | <b>164257</b>            | Power Kw:    | <b>77</b>                              |
| Bodytype:                         | <b>Break</b>             | Body color   | <b>Light Grey</b>                      |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                         |
| Transmission:                     |                          | Rims summer  | <b>Aluminium</b>                       |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                              |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>3823</b>                            |
| Number of doors                   | <b>5</b>                 |              |                                        |
| Number of seats                   | <b>5</b>                 |              |                                        |
| Number head rests                 | <b>5</b>                 |              |                                        |
| Rims summer                       | <b>Aluminium</b>         |              |                                        |
| Category                          | <b>Passenger Car</b>     |              |                                        |
| Oil level                         | <b>OK</b>                |              |                                        |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                        |

**Options**

|                              |                       |                   |
|------------------------------|-----------------------|-------------------|
| Radio CD                     | Central consol F      |                   |
| Windows electric F           | Luggage cover         |                   |
| Windows electric R           | Front parking sensors |                   |
| Cruise Control               | Rear parking sensors  |                   |
| Steering wheel multifunction | Type of Tow bar       | Tow bar removable |
| Type of headlighting         | Headlighting Halogen  |                   |
| Type of GPS                  | GPS big screen color  |                   |
| Type of Lining               | Lining fabrics        |                   |
| Type of climate control      | Autom climate control |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>215/55/16/97 V LightMetal</b> |                     |       |                     |
| Summer tyres: | Fr.L.                            | <b>Kleber: 5 mm</b> | Fr.R. | <b>Kleber: 5 mm</b> |
|               | Re.L.                            | <b>Dunlop: 7 mm</b> | Re.R. | <b>Dunlop: 7 mm</b> |

**Assistance equipment**

|             |            |
|-------------|------------|
| Spare wheel | <b>Yes</b> |
|-------------|------------|

|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Total cost ex VAT                                                   | 220,18 |
| Bumper R, Scratch(es), Acceptable                                   | 0,00   |
| No pictures to display                                              |        |
| Front bumper, Scratch(es), Acceptable                               | 0,00   |
| No pictures to display                                              |        |
| Wing R L, Scratch(es), Acceptable                                   | 0,00   |
| No pictures to display                                              |        |
| Bonnet, Stone chip(s), Acceptable                                   | 0,00   |
| No pictures to display                                              |        |
| Rearview mirror housing L, Scratch(es), Acceptable                  | 0,00   |
| No pictures to display                                              |        |
| Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 220,18 |

