



SKODA Octavia: 1GGS676

Vinnnumber:	TMBJG7NE6E0121071	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	4/02/2014	Fiscalpower:	105PK
Expertise Mileage:	88861	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3207
Maintenance	SERVICE -85D		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Compressor	Yes
Repair kit	No		

Total cost ex VAT	332,60
Protection plate M, Hole, E - Replace	32,60



Outer door handle R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display	
Maintenance book, Missing, E - Replace	0,00



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Registration Document, Missing, E - Replace	150,00
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Certificate Of Conformity, Missing, E - Replace	150,00
---	--------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display