


SKODA Octavia: 1JPN053

Vinnumber:	TMBJG9NE0F0130913	Versionname:	OCTAVIA COMBI Elegance
First Registrationdate:	2/02/2015	Fiscalpower:	105PK
Expertise Mileage:	209431	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2125
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/92 MS LightMetal			
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	593,24
-------------------	---------------

Seat cover F L, Stain, Cleaning	12,00
---------------------------------	--------------



Floor covering F L, Burned, Smart repair	64,32
--	--------------



Front bumper, Bump(s), It - Spot repair	115,56
---	--------



Tailgate, Bump(s) and scratch(es), It - Spot repair	115,56
---	--------



Protection plate M, Tear, E - Replace	62,00
---------------------------------------	-------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Seat cover R L, Stain, Cleaning	12,00
---------------------------------	-------

