



TOYOTA Auris: 1GRF440			
Vinnnumber:	SB1ZS3JE60E084474	Versionname:	AURIS TOUR.SP. HSD Lounge CVT 99PK Aut.
First Registrationdate:	7/04/2014	Fiscalpower:	
Expertise Mileage:	175276	Power Kw:	73
Bodytype:	Break	Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	3202
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/45/17/91 Y LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Dunlop: 3 mm	Re.R.	Dunlop: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			833,78
Wing R R, Bump(s), Acceptable			0,00
No pictures to display			
Wing F L, Scratch(es), LI - Repair and paint (complete)			220,18



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door frame R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door frame F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display