


**VOLKSWAGEN PASSAT : 1HCD328**

|                                   |                          |              |                  |
|-----------------------------------|--------------------------|--------------|------------------|
| Vinnnumber:                       | <b>WVWZZZ3CZEE145544</b> | Versionname: |                  |
| First Registrationdate:           |                          | Fiscalpower: |                  |
| Expertise Mileage:                | <b>87172</b>             | Power Kw:    | <b>77</b>        |
| Bodytype:                         |                          | Body color   | <b>Brown</b>     |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>   |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b> |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>        |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>3812</b>      |
| Battery functioning               | <b>Yes</b>               |              |                  |
| Number of doors                   | <b>5</b>                 |              |                  |
| Number of seats                   | <b>5</b>                 |              |                  |
| Number head rests                 | <b>5</b>                 |              |                  |
| Rims summer                       | <b>Aluminium</b>         |              |                  |
| Category                          | <b>Passenger Car</b>     |              |                  |
| Oil level                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                  |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Sun Roof electric     |                   |
| GPS storage                    |                              | Panoramic roof        |                   |
| GPS storage                    | <b>HD</b>                    | Central consol F      |                   |
| Windows electric F             |                              | Luggage cover         |                   |
| Windows electric R             |                              | Front parking sensors |                   |
| Cruise Control                 |                              | Rear parking sensors  |                   |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Seats F heated                 |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/97 W LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>511,91</b> |
|-------------------|---------------|

|                                          |              |
|------------------------------------------|--------------|
| Protection plate M, Missing, E - Replace | <b>15,00</b> |
|------------------------------------------|--------------|



|                                   |             |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

No pictures to display

|                                                                          |               |
|--------------------------------------------------------------------------|---------------|
| Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) | <b>115,56</b> |
|--------------------------------------------------------------------------|---------------|



Door R L, Bump(s), PDR - Knock out without painting

63,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35

