


FIAT Scudo LWB: 1ESM067

Vinnnumber:	ZFA27000064325820	Versionname:	SCUDO B/F LWB L-H1
First Registrationdate:	8/03/2013	Fiscalpower:	Deluxe 1200(EU5)128PK
Expertise Mileage:	208984	Power Kw:	94
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2728
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD	Rear parking sensors
Windows electric F	Type of Tow bar
Cruise Control	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/103 T Steel			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	681,15
--------------------------	---------------

Bodywork, Not original part, Acceptable	0,00
--	-------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Ignition key, Damaged, E - Replace	150,00
---	---------------



Steering wheel, Worn, Acceptable	0,00
---	-------------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
--	---------------



Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Damaged, E - Replace	300,00



Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Sliding door R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	