




VOLVO V70: 1ELF579			
Vinnnumber:	YV18W84A1D1267930	Versionname:	V70 D2 Kinetic St/St 115PK
First Registrationdate:	11/01/2013	Fiscalpower:	
Expertise Mileage:	128435	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4630
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunction	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	205/60/16/96 V LightMetal		
	Fr.L.	Michelin: 5 mm	Fr.R.
		Michelin: 5 mm	
	Re.L.	Michelin: 4 mm	Re.R.
		Michelin: 4 mm	

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	369,72
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Roof pillar L, Bump(s), It - Spot repair	115,56

