





VOLKSWAGEN Golf: 1HGR526			
Vinnumber:	WVWZZZAUZFP514478	Versionname:	GOLF VAR Highline 105PK
First Registrationdate:	16/07/2014	Fiscalpower:	
Expertise Mileage:	176033	Power Kw:	77
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4224
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Summer tyres:	205/55/16/91 V LightMetal		
	Fr.L.	Firestone: 5 mm	Fr.R.
		Firestone: 5 mm	
	Re.L.	Continental: 5 mm	Re.R.
Assistance equipment			
	Spare wheel	Yes	Jack
			Yes
	Total cost ex VAT		787,20
Door R R, Bump(s), PDR - Knock out without painting			159,00
 			
Wing R R, Bump(s), PDR - Knock out without painting			82,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Bump(s), PDR - Knock out without painting

63,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Stone chip(s), Windscreen repair

58,80



Internal Boot Lining L, Scratch(es), Acceptable

0,00

