



RENAULT Scenic: 1HAX544			
Vinnnumber:	VF1JZ14K650895064	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	6/06/2014	Fiscalpower:	
Expertise Mileage:	75363	Power Kw:	81
Bodytype:	Hatchback	Body color	Light Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2413
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 H Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	1501,42
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80



Door F L, Bump(s), Acceptable	0,00
No pictures to display	

Roof pillar L, Bump(s), LI - Repair and paint (complete)	220,18
	
Rearview mirror housing L, Scratch(es), Smart repair	110,64
	
	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
	
Roof pillar R, Bump(s), LI - Repair and paint (complete)	220,18
	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	
Door R L, Bump(s) and scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
	
Wing R L, Bump(s), Acceptable	0,00
No pictures to display	
Door F R, Bump(s), Acceptable	0,00
No pictures to display	
Bumper corner R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Bump(s), Acceptable	0,00
No pictures to display	
Tailgate, Bump(s), PDR - Knock out without painting	82,80
	
Wheel cover F R, Damaged, E - Replace	30,00

