


LU VOLKSWAGEN SHARAN: BB8830

Vinnnumber:	WVWZZZ7NZFV029583	Versionname:	2.0 TDI CR 103KW BMT HIGHLINE
First Registrationdate:	4/02/2016	Fiscalpower:	
Expertise Mileage:	129556	Power Kw:	103
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4117
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 9,9 mm	Re.R.	Dunlop: 9,9 mm

Assistance equipment

Emergency spare wheel	No	Jack	No
Total cost ex VAT			919,62
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Jack, Missing, E - Replace			42,00
<i>No pictures to display</i>			
Front bumper, Bump(s), LI - Repair and paint (complete)			254,16





Door F L, Scratch(es), E - Replace	0,00
------------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Seat cover R, Worn, Acceptable	0,00
--------------------------------	------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------



Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Wing F L, Bump(s), PDR - Knock out without painting	130,80
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display