



VOLKSWAGEN Passat: 1GXL751			
Vinnnumber:	WVWZZZ3CZEE146336	Versionname:	PASSAT BER Comfortline BMT 105PK
First Registrationdate:	27/05/2014	Fiscalpower:	
Expertise Mileage:	166816	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2714
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	215/55/16/97 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	1722,75
Bumper moulding R R, Damaged, E - Replace	14,40





Interior, Dirty, Cleaning	0,00
---------------------------	------






Wing R R, Bump(s), LI - Repair and paint (complete)

308,20




Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Hail damage, PDR - Hail

575,00



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Damaged, E - Replace


50,00



Roof, Hail damage, PDR - Hail

150,00





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display