



VOLVO V40: 1FCI078			
Vinnnumber:	YV1MV8481D2059785	Versionname:	V40 D2 Base 115PK
First Registrationdate:	23/05/2013	Fiscalpower:	
Expertise Mileage:	111671	Power Kw:	84
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4212
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			576,50
Rearview mirror housing L, Difference in color, Acceptable			0,00



Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Bad repair, Acceptable	0,00
No pictures to display	
Roof, Scratch(es), L L - Repair and paint (complete)	481,50

		
Alloy rim R L, Scratch(es), Acceptable		0,00
No pictures to display		
Rearview mirror housing R, Difference in color, Paint		0,00
		
Alloy rim F R, Scratch(es), Acceptable		0,00
No pictures to display		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		