


MERCEDES B: 1HFJ578

Vinnnumber:	WDD2462121J273948	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	8/07/2014	Fiscalpower:	
Expertise Mileage:	61863	Power Kw:	80
Bodytype:	Hatchback	Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE A5 305 DAGEN	Parking lot	1330
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Yokohama: 7 mm	Fr.R.	Yokohama: 7 mm
	Re.L.	Yokohama: 7 mm	Re.R.	Yokohama: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			511,56
Bumper R, Scratch(es), It - Spot repair			115,56





Headlight L, Scratch(es), E - Replace

396,00

