



BMW 3: 1HAG012			
Vinnnumber:	WBA3Y11090D449144	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	3/06/2014	Fiscalpower:	
Expertise Mileage:	125094	Power Kw:	100
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4208
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/50/18/95 W LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Runflat	Yes
Total cost ex VAT	369,80
Wing R L, Bad repair, Acceptable	0,00



Roof pillar L, Bad repair, Acceptable	0,00
	
Door F L, Bad repair, Acceptable	0,00
	
Windscreen, Stone chip(s), E - Replace	0,00
	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bonnet, Dent(s), PDR - Knock out without painting	63,00
	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	



Door R R, Scratch(es), Acceptable

0,00

No pictures to display