



BMW 5: 1GWL627				
Vinnumber:	WBA5J11010D336091	Versionname:	5 TOURING 518d 136PK	
First Registrationdate:	20/05/2014	Fiscalpower:		
Expertise Mileage:	169865	Power Kw:	100	
Bodytype:	Break	Body color	Dark Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:		Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	2732	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed	
Radio multimedia				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	225/55/17/97 Y LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			719,00	
Sill outer L, Scratch(es), Acceptable			0,00	
No pictures to display				
Door F L, Scratch(es), Acceptable			0,00	
No pictures to display				
Bumper R, Scratch(es), Acceptable			0,00	
No pictures to display				
Alloy rim R R, Scratch(es), Acceptable			0,00	
No pictures to display				
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16	



Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display