



MERCEDES CLA: 1HCH342				
Vinnumber:	WDD1173121N101081	Versionname:	CLA BER 180 CDI 109PK	
First Registrationdate:	17/06/2014	Fiscalpower:		
Expertise Mileage:	148499	Power Kw:	80	
Bodytype:	Berline	Body color	Black	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3303	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Front parking sensors		
Windows electric F		Rear parking sensors		
Windows electric R				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Yokohama: 4 mm	Re.R.	Yokohama: 4 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			42,00	
Door F R, Dent(s), Acceptable			0,00	
No pictures to display				
Bumper R, Scratch(es), Acceptable			0,00	
No pictures to display				
Door R L, Scratch(es), Acceptable			0,00	
No pictures to display				
Speaker cover R L, Broken, E - Replace			42,00	
				
Front bumper, Scratch(es), Acceptable			0,00	
No pictures to display				