



PEUGEOT 308: 1HFT375				
Vinnnumber:	VF3LCBHXHES143301	Versionname:	308 SW BlueHDi Allure STT	
First Registrationdate:	9/07/2014	Fiscalpower:	116PK	
Expertise Mileage:	138547	Power Kw:	85	
Bodytype:		Body color	Brown	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	OK	Parking lot	1208	
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
GPS storage		Central consol F		
GPS storage	HD	Luggage cover		
Windows electric F		Front parking sensors		
Windows electric R		Rear parking sensors		
Cruise Control		Type of Tow bar	Tow bar removable	
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT		1089,80		
Windscreen, Repaired, Acceptable		0,00		
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		356,20		



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80



Door F R, Dent(s), PDR - Knock out without painting 63,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Foglight L, Broken, E - Replace 138,00



Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------

