



BMW X1: 1FH0772

Vinnnumber:	WBAVN710X0VX05936	Versionname:	X1 sDrive18 136PK
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	130829	Power Kw:	100
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	12000	Parking lot	2415
Maintenance	JUNI 2019		
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS base	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

	Runflat	Yes
--	---------	-----

Total cost ex VAT	517,76
Bonnet, Scratch(es), 67 - Polish	0,00

 		Shutter / cover, Missing, E - Replace	5,00
 		Cigar lighter, Missing, E - Replace	18,00
 		Bumper R, Scratch(es), It - Spot repair	115,56
     		Tailgate, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display		Outer backrest protection R, Scratch(es), Acceptable	0,00
No pictures to display		Door R R, Dent(s), PDR - Knock out without painting	63,00
   		Bumper spoiler F, Scratch(es), E - Replace	42,00
 		Wing moulding F L, Scratch(es), E - Replace	14,40
 		Door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display		Side window trim F L, Scratch(es), Acceptable	0,00
No pictures to display		Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display		Seat cover F L, Worn, Acceptable	0,00



Bumper cover R M, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Outer backrest protection L, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Acceptable	0,00
No pictures to display	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror R complete, Scratch(es), Acceptable	0,00
No pictures to display	
Grill frame, Missing, Acceptable	0,00



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Repaired, Acceptable	0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Outer door handle R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F M, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror L complete, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	