



FIAT Ducato 35 LWB HR: 1EWR375			
Vinnnumber:	ZFA25000002365558	Versionname:	DUCATO 35 B/F LWB HR (EU5)130PK
First Registrationdate:	9/04/2013	Fiscalpower:	
Expertise Mileage:	140703	Power Kw:	96
Bodytype:	Transporter	Body color	Yellow
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV13
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Aluminium		
Category	Light Commercial Vehicle		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	NOT OK

Degree of wear				
Summer tyres:	215/70/15/109 S Steel			
	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	2519,62
Bumper F R, Scratch(es), Smart repair	110,64



Bumper R, Deformed / Strained, E - Replace	329,40
--	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)

158,85



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Trunk door panel L, Broken, E - Replace

50,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76





Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display

Internal Boot Lining R, Broken, Smart repair	110,64
--	--------



Trunk door panel R, Broken, E - Replace	50,00
---	-------



Rearview mirror L complete, Broken, E - Replace	138,00
---	--------



Internal Boot Lining L, Broken, Smart repair	110,64
--	--------



Door moulding Lower F L, Missing, E - Replace	91,50
---	-------



Wing trim R L, Missing, E - Replace	69,00
-------------------------------------	-------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Roof, Dent(s), LI - Repair and paint (complete)	361,13
---	--------

