



VOLKSWAGEN Golf: 1FLQ785

Vinnumber:	WVWZZZ1KZDK012173	Versionname:	GOLF CABRIO TSI 160PK
First Registrationdate:	8/08/2013	Fiscalpower:	
Expertise Mileage:	51451	Power Kw:	118
Bodytype:	Cabriolet	Body color	White
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Maintenance	NOT OK	Parking lot	3324
Battery functioning	Yes		
Number of doors	2		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 2,5 mm	Fr.R.	Michelin: 2,5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	220,00
-------------------	---------------

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Alloy rim F R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Maintenance, Maintenance, Execute	0,00
	
Wing F R, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Mirror side blinker R, Broken, E - Replace	30,00
	
Door F R, Dent(s), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L polished, Scratch(es), Acceptable	0,00
No pictures to display	