



BMW 1 HATCH: 1LSE891

Vinnnumber:	WBA1V91010V493048	Versionname:	1.5 116D
First Registrationdate:	20/11/2015		EFFICIENTDYNAMICS
Expertise Mileage:	73153		EDIT. (85KW)
Bodytype:	Hatchback	Fiscalpower:	
Gearbox:	MAN 6 VIT	Power Kw:	85
Transmission:		Body color	Grey
Fueltype:	Diesel	Paint type	Metalic
Battery functioning	Yes	Rims summer	Aluminium
Number of doors	5	Oil level	OK
Number of seats	5	Parking lot	4307
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1400,68
Door R R, Scratch(es), Acceptable			0,00

No pictures to display

Windscreen, Crack, E - Replace	487,20
--------------------------------	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	------

No pictures to display

Roof pillar L, Chemical polution, LI - Repair and paint (complete)	220,18
--	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------

