



PEUGEOT 508: 1FLX269

Vinnumber:	VF38E9HD8DL042817	Versionname:	508 SW e-HDi Allure BMP 115PK Aut.
First Registrationdate:	12/08/2013	Fiscalpower:	
Expertise Mileage:	134810	Power Kw:	84
Bodytype:	Break	Body color:	Beige
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2728
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting:	Headlighting Xenon	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/98 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			
Bumper R, Scratch(es), LI - Repair and paint (complete)			




Rear spoiler, Chemical polution, LI - Repair and paint (complete)



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 220,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display