


AUDI A4: 1GUH312

Vinnnumber:	WAUZZZ8K0EA146341	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	139836	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2708
Maintenance	+ 12400 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	DVD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1203,56
-------------------	----------------

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	---------------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------




Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display