



AUDI A3: 1FJF341			
Vinnnumber:	WAUZZZ8V3EA023711	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	120653	Power Kw:	77
Bodytype:	Hatchback	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3623
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunction			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 W LightMetal			
	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Pirelli: 8 mm	Re.R.	Pirelli: 8 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1248,62
Door R R, Scratch(es), LI - Repair and paint (complete)			318,35



Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Outer door handle F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

